





date: January 14, 2004

to: Distribution

from: A. Piper

subject: "Safety-Walk"

On Wednesday, January 7, 2004 at 13:00 hours, A "Safety-Walk" was performed focusing on a task to be carried out by the rigging crew.

## **Safety-Walk Attendees:**

*Arthur Piper (C-A ESHQ)* 

Peter Cirnigliaro (C-A ESHQ)

Alexander Pendzick (C-A F&ES Section Head)

Alex Korol (Rigging Supervisor)

Arthur Anderson (Rigging Lead Man)

R. Medina (Rigger)

G. Ghimiray (Rigger)

B. Cornell (hemo)

R. Johnson (hemo)

Task: Relocating shield blocks from building 912 to building 974 & Blockyard

## Positive Observations:

- Loads were strapped to the forklift masts
- *Hardhats were worn by the crew*
- Safety shoes were worn by the crew
- Crane operators inspect lifting slings prior to each use
- Gloves were worn by crew
- Forklift trucks are "ready" checked by operator at the beginning of each work shift
- A work order has been generated to install "D" rings on forklift trucks to enable riggers to strap the load more effectively to the forklift truck mast

## **Negative Observations:**

- Observers were not wearing hardhats
- *Use of seatbelts by forklift operators was inconsistent*
- Several of the hardhats in use by the crew were in service for many years and in some cases did not indicate ANSI compliance
- At the roll-up door in use, the blacktop in the proximity of the concrete apron is in poor condition
- Some of the older forklift trucks are not equipped with back up alarms
- The condition of one of the older forklift trucks was poor, with tires worn beyond normal service life
- There is no indication of inspection on the forklift trucks and concerns were raised as to if there is a program in place to service/inspect forklift trucks

Recommended corrective actions for negative observations will be assigned and tracked to completion in the ATS family tracking system.

Distribution: Safety-Walk attendees

R. Karol E. Lessard D. Lowenstein